

TH8P2

Circular Chart Recorder

-

0

100



FEATURES

- Digital Display
- Replaceable sensor
- 8" Chart (203mm)
- User selectable recording times and temperature ranges

ABOUT

The TH8P2 (equipped with field replaceable sensor) features a full 8" (203mm) temperature and humidity chart and a large digital display.

The digital display for this chart recorder provides quick reference of current and min/max conditions.





For more information, please refer to

T: +31 (0)174 287 160 E: info@vrsupplies.com W: www.vrsupplies.com

RECORDERS & DATA ACQUISITION



TH8P2

Circular Chart Recorder	
pecifications	
Ambient Operating RH Conditions: 0-95% RH non-condensing	
Ambient Operating Temperature Conditions: 32 to 120F (0 to 50C)	
Approvals: CE	
Battery Backup: Four AA Batteries. Powers unit for up to 3 Days.	•
Battery Life (Avg): 76 Hours (Back-up Only)	-
Calibration Options: N100, N300, N400	-
Channels: CH1: Temperature, CH2: Humidity	•
Chart Rotation Speed: 24 Hour, 7 Day or 31 Day	-
Dew Point Accuracy: +/-3.6F from 30 to 95% RH (Calculated)	-
(+/-2C from 30 to 95% RH (Calculated))	•
Dew Point Range: 32 to 122F (0 to 50C)	-
Dimensions: 3.1 x 9.2 x 9.2in	-
Display Dimensions Height: 1.375	•
Display Dimensions Width: 2.0	
Display Resolution: 0.1	-
Display Type: LCD	
Enclosure: Rugged Black ABS Case, Polycarbonate Door, Aluminum Dial	
Humidity Accuracy: +/-2% RH from 5 to 95%; +/-2% RH from 5 to 95%	•
Humidity Range: 0-95% RH non-condensing	-
Humidity Sensor Type: Field Replaceable	
IP Rating: 20	•
Included Accessories: AC Adapter, Red and Blue Pen, Four AA Batteries	-
and Quick Start Guide. *Charts sold separately.	-
Keypad Functions: Power On/Off, Pen Home	0
Mounting Options: Free Standing or Wall Mount (With Keyhole)	-
Power Cord: 6 ft	-
Power Source: 120 to 240 VAC, 12 VDC (INTL fittings available); AC Adapter	•
Power Status Indicator: LED Indicator	
Remote Sensor Length: Single 10 ft extension cable available	-
(without sacrificing accuracy)	
Response Time: 5 Minutes to 63% of Full Scale	
Temperature Accuracy: +/-0.8F from 32 to 120F (+/-0.44C from 0 to 50C)	-
Temperature Range: 32 to 120F (0 to 50C); 40 to 110F (5 to 40C)	•
Unit Weight: 4.6 lbs	
Units/Pkg: 1	-
Warranty: 12-Month Limited	•
	-

RECORDERS & DATA ACQUISITION



TH8P2

-

Circular Chart Recorder

Accessories



R180 – AC Adapter for TSB/TWE/TWP Loggers and KT8/KT6 series



R066 – Universal Plug Kit International plug kit for Data Loggers



A062 – 10' Extension Cable for R157 AC Adapter



A868 – Sensor Dust Filter prolong the life of your sensor



R200 – Temperature/Humidity Sensor A replaceable, angled sensor